


## 9 Type designation



### Order example of force sensor

Force sensor of H series, intended for force conversion from 0 to 100 N, with fitting thread M10x1:

Force sensor H 100-1.

Note: if wished, the wire length (standard 80 mm) can be changed, in this case the required length should be added to the wire code L, for example:

Force sensor H 100-1-L130.

## 10 Marking

Marking on the sensor body must contain following information: designation of the sensor and order number.

***Microtensor***

Force sensors H Series